

Address:

3036 AMBER WAVES LN WYLIE, TX 75098

As Of: 10/22/2024

Prepared For:MEGA CAPITAL FUNDING

Order ID: 10009755

Loan #: 892519

Inspection Type: FNMA UPD

Order Information

Inspection ID	a84e59820fae51ab9a966e40e0c96ec6	Submission Date	10/29/2024 19:28:53
Subject Address	3036 Amber Waves Ln	Borrower Name(s)	Johnson Henry Kulandaisamy
Lender Name	MEGA CAPITAL FUNDING		
AMC Name	CaptureData Test	AMC ID	1001
Inspection Type	FNMA UPD	Case File ID	
Data Collector	Anthony DeSilva	LPA Key	

Value Acceptance Property Data API Result

Status COMPLETE Submission Date 10/29/2024 15:33:26

Submission Result Messages

Message Type	Message	Code
Appraisal Requirement	Unable to perform further analysis. Please work with your lender partner to determine if one or more of the following needs to be resolved: DU casefile id, property address, or loan eligibility parameters. (Code: 99)	AppraisalRequirementsMes sages
Rule Messages	The view noted has material impact on the risk analysis.	FNM120

Exterior Photos



STREET VIEW RIGHT



STREET VIEW LEFT



ADDRESS NUMBER

Locations & Views

Name	Sub Type	View Quality	Description
Site Feature View	COMMERCIAL	PARTIAL	Docking area for Targer supermarket
Non Residential Use	NONE_OBSERVED		
Adverse Condition	NONE_OBSERVED		
Site Feature Location	RESIDENTIAL		Standard residential neigborhood
Property Improvement	COVERED_PORCH		front entry
Property Improvement	PATIO		back covered patio
Property Improvement	FENCE		Rear fence

Utilities

Туре	SubType	Off Grid
Electricity	PUBLIC	
Electricity	SOLAR	Yes
Gas	PUBLIC	
Water	PUBLIC	

Loan #: 892519 Order ID: 10009755

Туре	SubType	Off Grid
Sewer	PUBLIC	- -

Locations & Views Photos



COMMERCIAL



COMMERCIAL



COMMERCIAL



COVERED_PORCH



PATIO



FENCE

Car Storage - 1, BUILTIN_GARAGE, on Structure 1, Unit 1

Summary

Storage Type BUILTIN_GARAGE Parking Spaces 2 Garage SqFt 385

Conversion Indicator

.....

Car Storage Updates

NONE OBSERVED

Car Storage Deficiencies

No

Component	Deficiency Type	Detail Name	Severity	Description	
NONE OBSERVED					

Car Storage Photos



EXTERIOR GARAGE



INTERIOR GARAGE



INTERIOR GARAGE

Car Storage Photos



EXTERIOR GARAGE



INTERIOR GARAGE



INTERIOR GARAGE

Loan #: 892519 Order ID: 10009755

Structure - 1, DWELLING

Summary

Structure Type DWELLING Construction COMPLETE Attachment Type DETACHED

Status

Construction Type FRAME Foundation Type SLAB Structure Area 5459

(sf)

Contains RoomsYesYear Built2021Year BuiltNo

Estimated

Exterior Updates

NONE_OBSERVED

 Component
 SubType
 Update Timeframe
 Description

Exterior Deficiencies

Component	Deficiency Type	Detail Name	Severity	Description
NONE OBSERVED				

Structure Photos



STRUCTURE_FRONT



STRUCTURE_FRONT



STRUCTURE_FRONT



STRUCTURE_FRONT



STRUCTURE_REAR



STRUCTURE_REAR

Loan #: 892519 Order ID: 10009755



STRUCTURE_REAR



VIEW_FRONT



VIEW_LEFT_SIDE



VIEW_LEFT_SIDE



VIEW_RIGHT_SIDE



VIEW_RIGHT_SIDE

Loan #: 892519 Order ID: 10009755



VIEW_RIGHT_SIDE



VIEW_REAR



VIEW_REAR



STRUCTURE_LEFT_SIDE